



# Atera SIGNO

BMW  
2er Coupe (F22) 03/2014-




7





8

nur bei / only for Part-No.: 045 196



9





10

- nur bei Art.Nr.: 045 196  
only for part no.: 045 196
- |               |                 |
|---------------|-----------------|
| A- 9919700065 | 11- 9910700004  |
| B- 9945700111 | 12- 9908700010  |
| C- 9918700253 | 13- 9922700204  |
|               | 14- 9918700243  |
|               | 15a- 9949700742 |
|               | 15b- 9949700743 |
|               | 15c- 9949700743 |
|               | 15d- 9949700742 |
- |                |
|----------------|
| 1- 9945700090  |
| 2- 9919700062  |
| 3- 9945700105  |
| 4- 9912700051  |
| 5a- 9918700526 |
| 5b- 9918700527 |
| 6- 9918700250  |
| 7- 9918700249  |
| 8- 9910700004  |
| 9- 9908700231  |
| 10- 9908700222 |
- 11- 9910700004  
12- 9908700010  
13- 9922700204  
14- 9918700243  
15a- 9949700742  
15b- 9949700743  
15c- 9949700743  
15d- 9949700742
- TX30  
9904700387



# Atera SIGNO

BMW  
2er Coupe (F22) 03/2014-

Part-No. : 044 196  
Part-No. : 045 196






Part-No. : 044 196



# Atera SIGNO

BMW  
2er Coupe (F22) 03/2014-



# Atera SIGNO

BMW  
2er Coupe (F22) 03/2014-

